## Marion/Service

Website: www.tri-stateservicegroup.com

Marion/Service Roofing & Sheet Metal Company P.O. Box 1628, 1011 S.W. 33<sup>rd</sup> Ave., Suite 200 Ocala, Florida 34478 (352) 622-7256 Fax (352) 622-1466 E-mail: ocala@serviceroofing.com

CONTRACTORS FOR:
BUILT UP & SINGLE PLY ROOFING
SHEET METAL FABRICATION & ERECTION

STATE ROOFING LICENSE #CCC1328582

August 17, 2020

Charlie Jackson Facilities Management Director 915 SE 5<sup>th</sup> St. Gainesville, FL 32601

Re: Invoice # 7380 (Work Completed December 2019)

Mr. Jackson:

I am writing you in regards to an outstanding invoice for roof repairs performed by Marion/Service on the Agricultural Extension office. The work was done in accordance with our annual minor roof repairs contract.

The work began in July of 2019. It consisted of two parts: 1. Replace shingles on a portion of the roof and 2. Install new single-ply roof over the lower section. All work was completed per Alachua County specifications and local building codes.

Due to the type of structural decking under the roof system, special fasteners had to be used. The fasteners were on backorder and it took several weeks to get them. We also had to order special adhesive for the single-ply roof which was not readily available and thus caused further delays.

All work was completed in December 2019. I have included a copy of the invoice with this correspondence.

Please let me know if you require any additional information to process this invoice for payment.

Sincerely,

Jon Belcher President

## MARION/SERVICE ROOFING & SHEET METAL COMPANY PO BOX 1628 OCALA FL 34478 PHONE (352) 622-7256 FAX (352) 622-1466

**INVOICE # 7380** 

DATE:

8/17/2020

SOLD TO:

ALACHUA CO FACILITIES

915 SE 5TH ST

GAINESVILLE, FL 32601

SHIP TO: ALACHUA CO AG EXTENSION

JOB#

8199

PO#

2019-00000576

**NET 30** 

LABOR AND MATERIAL TO TEAR OFF AND REPLACE EXISTING SHINGLES WITH NEW; AND TO INSTALL PVC ROOF.

This billing includes all costs and mark-ups to perform the work as described including labor, material taxes, supervision, insurance, tools and equipment, shop and warehouse expense, vehicular costs, recordkeeping, dump charges, and environmental compliance.

SALES AMOUNT
MISC. CHARGES
SALES TAX
FREIGHT
TOTAL


7,900.00 included

7,900.00


Marion/Service Roofing & Sheet Metal Company will make repairs to localized areas that appear to be the source of leaks and will make a good faith effort to locate and try to stop leaks. Marion/Service Roofing & Sheet Metal Company does not warrant that further leaks will not occur. Depending upon the condition, age and type of roof, future roof leaks may well be expected. Contractor is not responsible for indoor air quality, interior or consequential damages, including mold, mildew, loss of use, damage to personal property, personal injury or claims from building occupants.




Roof Leaks SPR 2\$2\$



Roof Leaks SPR 2\$2\$





ROOF LEAKS