

# Emergency Certification Form

Date: November 21, 2019

Note: Complete this form with all pertinent information (Purchasing Policy Manual, Section 3-3, Emergency Purchases). Submit this form, a requisition and all emergency backup to Procurement.

Department: Public Works

Division: Road and Bridge

Account Charged:

|                                                      |        |                 |            |                    |
|------------------------------------------------------|--------|-----------------|------------|--------------------|
| 3 5 0 / 7 9 1 6 / 5 4 1 / 6 3 / 6 5                  | /      | /               | /          | /                  |
| (Fund) (Dept/Division) (Activity) (Element) (Object) | (Fund) | (Dept/Division) | (Activity) | (Element) (Object) |
| / / / / /                                            | /      | /               | /          | /                  |
| (Fund) (Dept/Division) (Activity) (Element) (Object) | (Fund) | (Dept/Division) | (Activity) | (Element) (Object) |

Authorized Department Signature:  Type Name: Ramon D. Gavarrete, P.E.


Digitally signed by Ramon D. Gavarrete, P.E.  
Date: 2019.11.21 14:11:50 -05'00'

Emergency Circumstances (Type In Your information for Printing): After the NW 43<sup>rd</sup> Street milling and resurfacing project, a void formed under the sidewalk and caused it to collapse immediately south of NW 51<sup>st</sup> PI. Additional investigation was needed to determine what was causing the void and it has been determined that the void was due to issues in approximately 350' of drainage pipe. A proposal was received 11/20/19 to clean out and place cured-in-place pipe (CIPP) liner in the existing 30" culvert. The proposal utilizes the annual contract prices with the City of Daytona Beach. Due to the possible immediate collapse of additional sidewalk sections and portions of the roadway, it is imperative to fix it quickly to limit the liability of the hazardous situation as additionally voids could exist under NW 51<sup>st</sup> PI and NW 51<sup>st</sup> PI or NW 43<sup>rd</sup> St could collapse due to the condition of the pipe.

Recommended Action (Type In Your information and Print):

\*\*\*\*\* Procurement Manager Use ONLY \*\*\*\*\*

☒ Approved
 ☐ Denied

  
 \_\_\_\_\_  
 (Procurement Manager's Signature)

11 / 21 / 2019  
 (Date)